



Detail where shear wall will lack continuity due to obstruction on wall..

Wall Obstruction Detail