



Shearwall Repair no blocking-flushcut repair

This is a repair to attach existing shear panel to mudsill when original contractor neglected to install blocks on top of mudsill.