



No framing anchors on existing shear wall
 Limited access to end joist
 prevents installation of framing anchors.