



No blocking between joists

Bolting of floor to foundation when mudsill is not accessible or when no mudsill is present and no blocking exists between floor joists

Sidebolt no blocking, 2x8 and 3/4 ply